











此步骤为试验车底盘是否能正常使用回力 灯光 音乐效果



This step is to check the function of pull back, light & music of car's chassis could be work successfully or not.




1





2






3




4





5





6





7





8





9




10



11





12





13

9




12





14





15





16





17




18





19




20



20



21






2x 2x 2x




22




1x 2x 2x 2x

23




2x 1x 2x 2x

24




2x 1x 1x 2x

25




1x 1x 1x

26




1x 1x4 1x 1x 1x

27




1x 1x 1x

28




1x 1x 1x

29




1x 1x 1x4 1x

30




1x 1x 1x 1x

31



32




31

27




1x 1x 1x

33




1x 1x 1x 1x

34




1x 1x 1x

35




1x 1x 1x

36




1x 1x 1x4 1x

37



1x 1x 1x 1x


38



39


34

38




1x 1x 1x 2x

40




2x 2x

41



1x 2x4 1x 1x 1x


42



43


42

39




4x

44




1x 2x

45




1x 1x8 1x 1x 2x 2x

46



1x 1x 1x 1x 2x

47



1x 1x 1x 2x

48

